

Comments for Mallard North Landfill Conceptual Gas Collection System

1. Please provide documentation as to how RMT determined that there is a crack in G-116 probe.
2. Will the condensate knockouts be placed in the waste mass or will they be placed above ground? If placed above ground, please describe how the knockouts will be winterized and how the spill containment will be constructed.
3. Given that there is evidence of pressurized methane near the pond located on the east side of the landfill, consider the installation of a new extraction well in this area and connecting it to the propose solar flare located at DV-6.